Municipal Buildings Strategic Plan
Advisory Committee
Minutes
Thursday, October 29, 2015
7:00pm
Town Hall South
3 Main Street, Newtown

THESE MINUTES ARE SUBJECT TO APPROVAL BY THE MUNICIPAL BUILDINGS STRATEGIC PLAN ADVISORY COMMITTEE

The Municipal Buildings Strategic Plan Advisory Committee held a regular meeting on Thursday, October 29, 2015 in the meeting room at Town Hall South. The meeting was called to order at 7:04pm.

Present: Chairman Jay Maher, Bill Brimmer, Walt Motyka, Scott Cicciari, Mike Marinaccio, Kathy Hamilton, Jim Filan, Rebekah Harriman

Absent: Michelle Ku, Paul Lundquist

Others Present: Geralyn Hoerauf of Diversified Management, Ken Best of DRA, First Selectman Pat Llodra, George Benson – director of planning, Christal Preszler- Grant Coordinator, one member of the press, and eight members of the public

1. Review and Approval of Minutes:

Motion: Jay Maher motioned to accept minutes. Bill Brimmer seconded. The motion was approved unanimously.

2. Report on CIP Recommendations to BOS on September 10th

Bill and Geralyn went to the Board of Selectman (BOS) meeting on September 10th and contributed to the discussion on the CIP recommendations. It was well received and ongoing discussion is anticipated. The recommendation was made to invest a substantial amount of money into the multi-purpose building over the next 5 years of the CIP and that no further money is put into any work done on the Hook and Ladder building after it is vacated.

3. Discussion with George Benson regarding FFH campus and other future Town Development

George Benson and Christal Preszler gave an overview of the FFH campus. The white houses and green houses have been most recently demolished on campus. They will be renovating a duplex (#63 on map) that is expected to be done in spring of 2016. The community center location will be between the Newtown Youth Academy (NYA) and Canaan House. Woodbury Hall is the approximate size of the estimated needed space for the police department – just for reference of what a building built for the police station might look like. – Approx. 1400 square feet on one floor.

Scott asked about if there were thoughts when the FFH master plan was put together about potentially putting the police department on the campus. George answered that it was initially discussed but it never went further and it fell off the radar.

Kathy asks if there were other groups on the radar of the planning office that may be in need for a space. George suggests Plymouth Hall as a viable building for renovation. There is a theater, classrooms, as well as a gymnasium located in that building. It would be expensive to abate it and clean it up, but it's one of the only viable buildings on the campus. Abatement and demolition costs together would probably cost somewhere between \$2-4 million. Plymouth Hall is approximately 52k square feet including the gym, or 34k without the gym.

Woodbury Hall's footprint is between 10-14k square feet. Stratford Hall's footprint is approximately 4k square feet. They were hoping to get some sort of restaurant in Stratford Hall. More event fields will go in by Kent House once it is demolished.

4. Presentation of Further Analysis of Town Hall South as PD Headquarters

Currently, the police department is occupying the top floor of Town Hall South. It may be possible, with renovations, to make Town Hall South work if they are able to use the entire building. On the "Reuse of Town Hall South as the Police Department" handout, the hatched out areas on the blueprint are areas which would need further work. These proposed plans do not accommodate the dispatch area. It also does not include the shooting range which is a key part of what the police were looking for. There is a possibility to construct a shooting range below grade in the front of the building. Lieutenant Kullgren states that the police department had been using an outdoor range in Stratford, but that that facility is no longer in use. Law enforcement in the state of Connecticut are required a certain amount of hours to practice and qualify. Over the last 3 years, outdoor ranges are becoming harder to find. The officers need to be paid for the travel to a shooting range that is not local. Currently they are using the shooting range facility at FCI in Danbury.

Pat Llodra suggests that a cost/benefit analysis of a shooting range should be done. This is an issue that the Town of Bethel is currently struggling with so it would do the town well to be ahead of this by doing an analysis in advance.

The dispatch would not necessarily need to be a separate location from the police department, but there is a request that there is more of a defined separation of space between the police department and dispatch center.

Jim Filan states that it seems like 10 lbs. are trying to be put into a 7 lb. bag by trying to make the needs of a new police station fit into town hall south. Upgrades are needed to THS in order to make the police department an updated and usable building, but it would still be lacking in a few areas including no shooting range and no space for the dispatchers. THS doesn't work for the police department.

Kathy Hamilton asks what it would cost to build a new building for the police department. It is estimated at \$11,355,940 which does include a shooting range. It is everything they would need at a lesser cost than renovating THS. It would take approximately 18 months to build new but 2 years to renovate THS.

The biggest liability with THS is the parking. There is no ability to add more parking spaces for this building.

What are the borough restrictions on THS property if and when it is no longer a municipal building?

If the police department is relocated what happens with the THS building. Where would the social services department go? Park and Rec will hopefully have office space in the community center.

Plymouth Hall and Woodbury Hall should be added to the scope of this committee.

A recommendation should be made to the Board of Selectman at their next meeting on November 16th.

Motion: Jim Filan motioned to recommend to the Board of Selectman that Town Hall South not be renovated for the purposes of the Police Department based on the numbers given at today's meeting. Kathy Hamilton seconded. The motion was approved unanimously.

5. Public Comment

Paul Mangifico of Kent Road and the current chairman of the police commission thanked the committee for the recommendation.

Next meeting date to be determined for early December.

Motion: Jim Filan motioned to adjourn the meeting at 9:40pm. Scott Cicciari seconded. The motion was approved unanimously.

Meeting adjourned at 8:38pm

Respectfully Submitted, Aileen Barreto, Clerk

Presentation to Municipal Buildings Strategic Plan Committee Fairfield Hills

October 29, 2015





Fairfield Hills Campus History



History

- Built beginning in the 1930s
 - 185 acres
- Purchased by the Town of Newtown in 200431 buildings existed



10/29/2015





Fairfield Hills Campus Master Plan / Vision



Master Plan Update 2013

 Created a vision for the Fairfield Hills campus, "as a vibrant sustainable destination where professional offices would be nestled harmoniously within a core section of the campus. The all members of the community can go to enjoy recreational, social, cultural, and indoor and well-designed campus would connect the history of the site with its future, with the town outdoor activities. The campus would provide a home for **some municipal services** and a gathering place for a variety of town-wide events. Small retail stores, restaurants, and maintaining overall control of the property and preserving the campus environment and architectural style ".









Fairfield Hills Campus Buildings



Demolished

- Greenwich House
- Litchfield House
- **Bridgewater House** Fairfield House
- Yale Lab
- Danbury Hall

Projects Underway


- Single family houses –demo
- Duplex #63 renovation
 - Greenhouse demo
- Canaan House remediate / demo
- (Community Center)

Built

- Newtown Youth Academy
- Newtown Volunteer Ambulance
- Emergency Operations Center

Renovated

- Bridgeport Hall Newtown Municipal Center
- Engineer's House Newtown Recovery and Resiliency Team



		,

Program Description

Reuse of Town Hall South as the Police Department


The current Police Department occupies the entire upper level and a small portion of the lower level of Town Hall South. In this option the conversion of the entire building is explored to meet the programmatic needs of the Department but it is known that the current floor area is inadequate.

The east end of the building is not fully developed with two thirds of the Lower Level a fenced in enclosure and the upper level with just a floor slab that has been roofed over. These appear to be the best areas to achieve additional floor area. Walls can be added to replace the fence around the lower level and a complete enclosure provided at the upper level. There is no other opportunity to expand the floor area. (Typically a vertical addition might be an option but will require extensive renovations to transfer the loads from the new 2nd floor to new footings in the basement and to upgrade the building to resist seismic loading. The expense of such a scheme will be prohibitive and may create zoning problems).


Unfortunately, there is no opportunity to expand the parking area, but with the Police the only building occupant it could be argued that they will have an effective increase in parking.

With the added floor area the Police space needs can be accommodated at Town Hall South with two exceptions; firstly, the dispatch area will need to be relocated out of the building and secondly, the shooting range cannot be accommodated in the building. Any expansion of the building will extend over the setbacks, but it may be possible to have a lower level expansion, below grade, to accommodate the range. Below grade, it may be possible to obtain a variance to the Zoning By-Laws.

This appears to be a viable option for the Police Department but will require further exploration to determine if compliance with Zoning can be achieved.



1/16" = 1'-0"



2 LOWER LEVEL 1/16" = 1'-0"

		*
		•

Program Description

Police Department

It has been 25 years since the former tractor sales building was rehabilitated as the Police department on the upper level and town department space on the lower level. The most noticeable deficiency of this location is the lack of parking with it being almost filled during normal business hours. There is no space to expand this crucial part of the facility.

The portion of the building dedicated to the Police Department has many challenges to its continued operation. Examples include:

- Mechanical system does not function properly in either low or high temperature.
- Windows that have not been replaced leak air causing discomfort.
- The IT room is grossly undersized and there is no space for the IT Director. This is an area of much growth.
- The cell block is antiquated with inappropriate swinging doors, non-accessible shower rooms and it is significantly undersized.
- Sanitary sewer line in the cell area routinely becomes blocked.
- There is a gross lack of evidence and general storage.
- There is no space for a workout facility.
- The training room is the only space available for general use and as a consequence, is used for training, report writing, meetings, lunch room, break room and other activities not supported by the current building.
- There are no sleeping facilities, which may be necessary for times of bad storms.
- There is no munitions training facility.
- Building is not accessible to persons with disabilities.

For the program needs of the Police Department the 2008 study for the building was reviewed and then modified to reflect the current and future needs of the next twenty years. This was supplemented with the review of actual police department plans for other similarly sized communities.

The following chart was distributed to the department for review of the actual spaces needed and the chart modified based upon this input.

The current department includes the Communications (Dispatch) space, but due to the introduction of new State requirements a regional Communications department will be required. For the purpose of this study we have treated Communications as a separate building, but this could be connected to the Police Building.

The developed area of the site has been maximized with no available space for an expansion. To the rear of the site there are wetlands that prevent any expansion.

Currently the site has 51 parking spaces. Should the building be reused as commercial office space there will be a need for 54 spaces. The extra three spaces can be accommodated in the currently fenced-in area under the deck.

SPACE NEEDS ANALYSIS AND ASSESSMENT - INTERIOR

· Nooti4

The following pages list the typical spaces found in municipal law enforcement facilities designed today. A brief description of the characteristics, adjacencies and other features has been provided along with a comparative analysis of the existing square feet in the Newtown Police Department and the recommended area to meet customary requirements for a similar sized police force. We hasten to point out that there are no national space standards to use as a guide for this comparison. Discussions with the International Associates of Chiefs of Police confirmed the difficult task of establishing such space standards when the type of policing and particular needs of each community being served are taken into account. Therefore, the column titled "RECOMMENDED SQUARE FEET" has been derived from our lengthy experience in designing public safety facilities and represents our best professional judgment at this early stage in determining your department's needs.

SPA	CE DESCRIPTION	EXISTING	2008 STUDY	RECOMMENDED
1.	Public	SQUARE FEET	SQUARE FEET	SQUARE FEET
1.	Vestibule	96	80	80
	- Air-lock vestibule	90	80	00
	- Walk off mat			
	- Automatic opening doors			
	Electronic lock-down capability door controls to Main Desk			
	- 24/7 /365 access to facility for services			
	- 24/1 /303 access to lacility for services			
2	Lobby / Reception / Waiting		375	350
	- Access to Main Desk / Dispatchers			
	- Access to Records Clerk			
	- House Telephone			
	- Public seating for 8-10			
	- Display Case			
	- Pamphlet Rack			
	- Tackboard			
	- Electric water cooler / drinking fountain		i or an	
			1.0	
3	Public Toilets One (1)	30	150	80
	- Handicapped Accessible			
	Male & Female facilities to support Training Room		* ~ 7" 1 P	
	occupancy			
	e to make the part to the contract of		St. 10. v n	
4	Interview Rooms One (1) @ 65; One (1) @85	90	150	150
	- Public fingerprinting, (AFIS machine)			
	- Public and internal access		B Darley L.	
	- No windows to Lobby			
	- Electric door controls, doors controlled from Main Desk/Records		S.P. in so	
2.	Training Classroom			
1	Location / Function	MATERIAL STATE OF THE STATE OF		
	- Direct access for public from Public Lobby			
	 Access to public restroom facilities 			
	 Dual use as Emergency Operation Center, no natural light 		II	
	 Accommodate meetings of Police Commission, community 			
	outreach functions, station meetings, advancement			
	ceremonies, etc.			
2	Classroom	550	1,500	1300
	- Seating for one hundred (100) in chairs		A 74 2 11 11 11	
	 Projection screen with overhead video projection 			

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
	 Smart board technology in front of room Independent sound system, wireless microphones, amplifier Lighting on dimmers, varied lighting levels Cable TV service Dual use as redundant Emergency Operations Center emergency generator power data jacks and radio communications remote console jack telephone jacks Video input and output locations for cable broadcast Internet access, docking station for laptops COLLECT terminal location (restricted access) Movable tables and chairs 	Contractions of the second of		
3	Kitchenette		65	50
* 1	 Adjacent to Training Classroom Refrigerator / Freezer Microwave Sink Casework storage 	regist of		
4	Furniture Storage	120	120	125
	 Adjacent to Training Classroom Table / Chair storage on portable racks Sound system amplifier head end 			
3.	Main Desk / Complaints and Information			
	Computer workstation for one (1) Bullet resistant transaction window to Public Lobby, fixed style Intercom to Public Lobby Visual contact to Dispatch Center / console positions	issas la cocco	65	65
4.	Communications Dispatch Center – To be regionalized – see separate programming report.			
Tell	Location			
	 Adjacent Main Desk – Public Lobby Restricted access to Police Personnel 	1900		10.3 8
2	Dispatch Center	390	475	0
	 Console positions: three (3) active (2 active and 1 supervisory console), one (1) future console for regionalization Supervisory console with operable glass partition to Dispatch Center Redundant console design with monitors, telephone, data, radio, door controls, intercoms, and systems monitoring. Ergonomic console design with environmental controls Central Dispatching of Police, Fire, EMS Monitoring of municipal fire and burglar alarms E911 service to be provided to three (3) console positions Monitoring of CCTV surveillance / building security systems Locker storage for dispatchers (full height lockers) Independent HV AC unit Lighting on dimming controls Bookshelving / Manuals storage 			

SPACE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
 Window treatments on windows Acoustic treatment on walls, floors and ceiling NFPA 1221 recommendations preferred Markerboard / Tackboard Raised access flooring for wire management to consoles Digital voice recorders Console positions to have intercom to Main Desk transaction window 			
Video / Audio contact with detention facilities Paper shredder Photocopy machine / fax machine / scanner Cable TV access at console positions	en sun sport i en en sus en su en en de Marine	And	
3 Director of Communications - Workstation for one (1) with radio capabilities - Coat closet - Remote location from Dispatch Center - Shared interview / meeting space within department - File storage	90	225	0
 Visitor's chairs for two (2) Bookshelving / Manual storage Markerboard Copy machine (small) 	W/30 G/5	75	
Restroom Handicapped accessible Within second Communications Dispatch Center area		75	0
5 Kitchenette - Refrigerator / Freezer - Apartment sized stove / range / exhaust hood - Microwave - Sink I Disposal - Seating area for four (4) - Casework storage - Floor drain	135	80	0
6 Communications Equipment Room - E911 equipment / UPS - Demarcation point for telephone system - Access control head end - Halo ground loop - Conduits to Communications Dispatch Center for wire management - Rack mounted data equipment - Dedicated HVAC system - Emergency power supply - UPS system - FM-200 fire suppression system in lieu of wet system	50	300	0
Records Division Public Information Counter Bullet resistant transaction window to Public Lobby, sliding type with deal tray Intercom to Public Lobby Computer workstation		w/in Public Lobby	

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
	- Casework storage and countertop			
	- Adjacent to Public Lobby			
2	Police Information Counter	Control Standard	w/in Police Corridor	
	 Utilize for staff inquiries to Records Division Counter work area 			
	- Glass transaction window, sliding type			
	- Adjacent to files and photocopy area			
3	Office / Work Area	300	400	400
	 Workstations for four (4); three (3) clerks and one (1) manager Coat closet 		" = 3	
	- Casework storage			
	- Central work counter	STATE OF STREET		
	- Photocopy machine, paper storage, paper shredder			
	- Restricted access to staff			
8 2	- Adjacent to Public and Police Information Counters, files		2	
4	File Storage	130	200	200
	- File storage equal to 2X current filing capacity			
	- Utilize for both active and archive file storage			
	- Adjacent to Office / Work Area			
	- Utilize high density file storage system			
6	Administration			
6.				
6.	Chief of Police	220	280	220
	Chief of Police - Workstation for one (1)	220	280	220
	Chief of Police - Workstation for one (1) - Coat closet	220	280	220
	Chief of Police - Workstation for one (1) - Coat closet - Natural light	220	280	220
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage	220	280	220
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service	220	280	220
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage	220	280	220
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service	220	280	220
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage	220	280	370
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1)			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2)			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room - Police service reports and			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage			
	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room - Police service reports and Fingerprint files: four (4) cabinets	180	500	370
2	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room - Police service reports and Fingerprint files: four (4) cabinets Conference Room - Seating for eight (8) at conference table			
2	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room - Police service reports and Fingerprint files: four (4) cabinets Conference Room - Seating for eight (8) at conference table - Projection screen	180	500	370
2	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room - Police service reports and Fingerprint files: four (4) cabinets Conference Room - Seating for eight (8) at conference table - Projection screen - Cable TV service	180	500	370
2	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room - Police service reports and Fingerprint files: four (4) cabinets Conference Room - Seating for eight (8) at conference table - Projection screen - Cable TV service - Shared use with department, access to corridor	180	500	370
2	Chief of Police - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for three (3) at table - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room Captains (Two) - Workstation for one (1) - Coat closet - Natural light - Visitor's chairs for two (2) - Bookshelving / Manual storage - Cable TV service - File storage - Adjacent to Conference Room - Police service reports and Fingerprint files: four (4) cabinets Conference Room - Seating for eight (8) at conference table - Projection screen - Cable TV service	180	500	370

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
	Administrative Clerical / Reception			
8	- Executive Assistant workstation for one (1) adjacent to Chief of			
-	Police			
	- Administrative Assistant workstation for one (1) within open work			
	area			
	- Coat closet			
1,80	 File storage cabinets, personnel files adj. to Exec. Asst. 			
	The delage dubinote, percentile mod daj. to Exce. 766t.			
5	Workroom		225	200
-	- Copy / Fax Machine		220	200
	- Office supply storage cabinets			
	- Sink			
	- Microwave			
	- Undercounter refrigerator			
	- Paper shredder			
	- Work counter			
	- Adjacent to Administrative Clerical, Administrative Offices			
6	Toilet	45	75	60
	- Toilet, sink		7.0	00
	- Adjacent to Administrative Offices			
	Adjacon to Administrative Offices			
7.	Administrative Lieutenant			
1	Administrative Lieutenant	230	225	185
	- Workstation for one (1)		9.1	
	- Coat closet			
	- Natural light			
	- Visitor's chairs for two (2)			
	- Bookshelving / Manual storage			
	- File storage			
	- CAD monitor and full radio capabilities			
	- Adjacent to Administrative Offices			
8.	Operational Lieutenant			
1	Operational Lieutenant		225	185
	- Workstation for one (1)			
	- Coat closet			
	- Natural light			
	- Visitor's chairs for two (2)			
	- Bookshelving / Manual storage			
	- File storage			
	- CAD monitor and full radio capabilities			
	- Adjacent to Administrative Offices - Personal property lockers			
	(one per cell)			
0	Administrative Courses			
9.	Administrative Sergeant	400		
1	Administrative Sergeant	100	175	150
	- Workstation for one (1)			
	- Coat closet			
	- Natural light			
	- Visitor's chairs for two (2)			
	- Bookshelving / Manual storage			
	- File storage			
	- Training / Accreditation file storage	STATE OF THE PARTY		
	- Adjacent to Traffic Unit			
	143	(10)		

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
10.	Detective Division	NEWS CONTROL STATE		THE STATE OF THE S
1	Detective Lieutenant	80	225	185
	- Workstation for one (1)			100
	- Coat closet			
	- Natural light		See	
-	- Visitor's chairs for two (2)			
	- Bookshelving / Manual storage			
	- File storage			
	- CAD monitor and full radio capabilities	and the same of th		
1.5	- Vision panel from Office to Work Area			
	- Adjacent to Detective Sergeant			
	•		p = 0 = 0	
2	Detective Sergeant		175	150
	- Workstation for one (1)		**	
	- Coat closet		4.3	
	- Natural light			
	- Visitor's chairs for two (2)		a 4.5	
1	- Bookshelving / Manual storage		9.0	
	- File storage			
i de	 Vision panel from Office to Work Area 		7	
	 Adjacent to Detective Division Work Area 			
	Obstack Decorption			
3	- Workstation for one (1) at entry location to Detective Division		175	175
	Waiting area for three (3)File storage			
100	- Vision panel to Work Area			
	- Acoustic separation from Work Area			
	- Acoustic separation from Work Area			
4	Work Area	380	1,000	800
	- Workstations for ten (10)			
¥	- NCIC / COLLECT computer workstation		W.	
	- Coat rack		. Fi	
	- File storage, min. one (1) per workstation			
	- Bookshelving / Manual storage		_	
	- Counter work area			
	 Visitor's chairs, one (1) per workstation 			
_	Interview Deems Ture (2) @ CF	90	400	400
5	Interview Rooms Two (2) @ 65 - Table seating for three (3)	80	130	130
	- One-way vision panel to Monitoring Room			
	Video / audio concealed recording equipment			
	- "IN -USE" indicator light outside of rooms			
	- No vision panels in doors			
	110 violoti patitolo ili acoto			
6	Monitoring Room		50	50
	- Positioned between Interview Rooms (2)			
	- One-way vision panels to Interview Rooms (2)			
	- Lighting controls on dimmers			
	- No natural lighting or vision panels on doors		~	
	 Visual / audio monitoring equipment and recorders 			
	- Casework storage for equipment			
_	F :	10 ST 12 ST ST		
7	Equipment Storage Room	170	120	120
	- Secured storage of Detective Division equipment and supplies			

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
	Power supply for recharging of electronic equipment Adjustable shelving Adjacent to Detective Division			
11.	Traffic Unit			
	Traffic Unit	800	275	275
	 Workstations for two (2) File storage Computer workstation for one (1) Adjacent to Administrative Sergeant 		ár x	
2	Equipment Storage		50	50
	 Secured storage of fleet equipment, supplies Adjustable shelving Adjacent to Traffic Unit 		e: :	
12	Crime Prevention Office			
1	Crime Prevention Office		150	130
	 Workstation for one (1) File storage Computer workstation for one (1) Adjacent to Detective Division 			
2	Equipment Storage		50	50
	 Secured storage of marketing materials, pamphlets, flyers, etc. Adjustable shelving Adjacent to Crime Prevention Office 	The Cartesian		
13.	Technology Coordinator			
1	Technology Coordinator		200	120
	 Workstation for one (1) Computer workstation for one (1) Coat closet File storage Visitor's chairs for one (1) Bookshelving / Manual Storage Adjacent to Computer Equipment Server Room 		9 - EA - E - E - E - E - E - E - E - E -	
14.	Computer Equipment Server Room			
	Types of Computers			
	Central file server with patch panels to remote terminals UPS system Networked System of terminals / printers / copiers / scanners	Total of the control	2 y .	
2	Computer Equipment Server Room	145	250	80
	 Networked file server, rack mounted with patch panels Computer backup tape storage, fire rated storage FM-200 fire suppression in lieu of wet system Dedicated HV AC system No natural light Adjacent to Technology Coordinator, access controlled 	The poor		
3	Networked Data Rooms		65	65
	 Rack mounted patch panel locations on all floors Conduit connections to all data rooms and Server Room 		2	

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
7.2	 Conduit connections to Communications Equipment Room Stacked configuration on each floors preferred 			
15.	Patrol Functions			
1	Patrol Lieutenant		225	180
	- Workstation for one (1)			
	- Coat closet			
	- Natural light			
	- Visitor's chairs for two (2)			
	- Bookshelving / Manual storage			
	 File storage CAD monitor and full radio capabilities 			
	- Adjacent to Patrol Sergeants			
	Adjustite in all of odificality			
2	Patrol Sergeants	190	800	725
	- Workstations for eight (8)			
	- File storage, min. one (1) per workstation			
	- Key cabinet			
	- Visual monitoring of Briefing / Roll Call room			
	- Adjacent to Briefing/ Roll Call			
3	Patrol Sergeant Storage		100	100
	- Secured storage of patrol equipment		100	
	- Adjustable shelving			
-	- Adjacent to Patrol Sergeants work area			
4	Briefing / Roll Call	345	300	450
	 Accommodate fourteen (14) at training tables and chairs, Podium area at front of room 			
	Recharge rack area for spare equipment, tasers, radio charger			
	stations			
	- Markerboard / Tackboard			
	- Cable TV service			
	·			
	TOTALDIO			
5	Locker Rooms	900	1,950	1700
	- Male Locker Room to accommodate up to sixty (60) lockers			
			3	
			13	
	- 5. Female showers:			
	a. Two (2) minimum, individual shower compartments			
	- Full height mirrors at locker locations			
5	 Cable TV service CCTV monitor Projection screen with overhead video projection Casework storage Patrol mailboxes for distribution of mail / correspondence, lockable Locker Rooms Male Locker Room to accommodate up to sixty (60) lockers Female Locker Room to accommodate up to fifteen (15) lockers a. Locker sizes: 36" w. x 24" d x 72" h. b. Wooden bench with operable drawer under (36" x 36" x 18") 4. Male showers: a. Three (3) minimum, individual shower compartments b. One (1) designed for handicap accessibility 5. Female showers: a. Two (2) minimum, individual shower compartments b. One (1) designed for handicap accessibility Sink area with mirrors / soap / paper towel dispensers Toilet area with toilet partitions and toilet accessories Robe hooks at shower areas Shoe shine area Wet garment drying area 	900	1,950	1700

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
6	Physical Training Room		400	400
	- Designed for stationary equipment, no free weights		400	400
-	- Ceiling clearance for weightlifting			
9,,	- Drinking fountain		*	
	- Mirrored wall surfaces			
	- Rubber gym flooring			
	- Adjacent to Male and Female Locker Rooms			
7	Lunch Room / Day Room	345	300	400
	- Range with exhaust hood		000	
	- Microwave			
	- Sink with disposal			
	- Refrigerator / Freezer with ice maker			
	- Storage cabinets	PACES OF		
	- Vending machines: two (2) minimum			
	- Lounge area seating for ten (10)			
	- Locate adjacent to Patrol Functions			
8	Laundry Service		65	65
"	- Drop off / Pick-up area near staff entry location			00
	- Clothes bar and shelving			
	- Clothes hamper location			
	- Access controlled			
9	Quartermaster Storage		65	65
	- Secure storage of uniforms, leather goods, supplies, spare			
	equipment - Adjustable shelving			
-	- Access controlled			
	7,00000 00111011000			
10	Report Preparation		200	200
	- Computer workstations for up to five (5)			
	- Networked printers and copiers			
	- Forms storage shelving		2	
	- Copy machine			
	Paper shredderResearch library shelving			
	- Markerboard / Tackboard		4:	
	- CCTV monitors, wall mounted			
	- Adjacent to Patrol Functions, Patrol Sergeants			
	,			
11	Emergency Sleeping Area			350
	- Cots for Officers (3)			
	33.3 (3) (3)(0)(3)			
12	Bike Storage			75
16.	Union Space			
1	Union Space		65	
	- Workstation for one (1)			
	File storageIndependent telephone line			
	Tackboard adjacent and within staff area			
1	radhibbara dajadont and milini dan arda	the state of the s	I.	PER HOSELFORINGE PER HISTORY

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
17.	Indoor Firearms Training Range	Broken and a second		
1	Indoor Firearms Training Range		1,500	1500
	 Length of range: 75' minimum training distance Number of stalls: Four (4) minimum No floor drains Security baffles at ceiling 		1,300	1300
	 Varied lighting levels on dimmers Acoustic separation from adjacent spaces Independent HV AC system with filtering and humidity controls Rubber style, inclined backstop Individual shooting stanchions with range controls and intercom / audio 			
2	Ready Room		175	175
	 Countertop area Visual monitoring of indoor firearms training range Acoustical separation from range Adjacent to Indoor Firearms Training Range and Armory 			
3	Control Room		120	50
2	 Visual monitoring of training range and ready room Audio intercom system to firing line Lighting controls for training range Computer console for range controls, networked to shooting stanchions Console counter area Adjacent to Indoor Firearms Training Range and Ready Room 	Hazzrai I		
18.	Armory / Arsenal			
1	Armory / Arsenal - Storage of department issued firearms / ammunition, lockable - Gun cleaning counter - Canopy exhaust hood with light at gun cleaning area - Secured access to room - Floor drain - Storage cabinets - Equipment storage - Gun cleaning supply storage - Adjacent to Indoor Firearms Training Range	120	150	150
19.	Sally Port	200		
1	- Accommodate two (2) vehicles, drive thru configuration preferred - Ambulance accessible - Door leading to Prisoner Processing - Door leading to Juvenile Processing area - Floor drains with grease / oil separator - CCTV and audio monitoring - Interlocked doors at exterior and prisoner processing - Hose bibb - Overhead coiling doors controlled through Dispatch - Service sink within Vehicle Processing area - Pistol lockers at points of entry into facility - Carbon Monoxide detection system with exhaust fan	300	900	800

SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
	Eye wash and emergency showerNo washing of vehicles anticipated			
2	Road Supply Storage		150	150
-	- Flare storage		130	130
	- Cones, barricade storage			
	- Road supply storage		,	
	- Traffic control equipment storage			
	- Wire mesh partitioning from Sally Port area			
20.	Prisoner Processing			
1		140	500	300
	- Secured door to Sally Port			
	- Secured door to Corridor			
	- Pistol lockers at points of entry			
	- Holding room for booking purposes, wire mesh enclosure			
	- Booking counter with computer workstation, mugging camera		9 00	
	 AFIS fingerprinting station adjacent to Holding Room CCTV and audio surveillance of all areas, minimize blind spots 			
	- Duress alarms at varied locations			
	- Eliminate hard comers and edges			
	- Hose bibb (secured)		4:	
	- Personal property lockers (one per cell)			
2	Toilet Room	40	50	F0
	Security penal fixture with remote flush capability	40	50	50
	- Lighting and water controls outside of room			
	- Reverse door swing	A STATE OF THE PARTY OF		
	- Shower (industrial type) with tempered water			
	- Floor drain			
3	Intoximeter Room		80	70
	Deep counter with intoximeter equipment, adjacent bench area		- 80	70
	- Inaccessible power and data outlets			
	- Dual use as Interview Room			
	- Table seating for two (2)			
	Briganay / Visitay Booth		75	
-	Prisoner / Visitor Booth - Reverse swing on door		75	75
	- Eliminate hardware on interior side of door		· ·	
	- Fixed transaction window with bullet resistant glass and			
	contraband baffle			
	- Secure bench bolted to floor			
	 Impact resistant lighting with lighting controls outside of room(s) 	Control of the same of		
5	Prisoner Release Area		N/A	
	- Utilize Public Lobby for prisoner release area		3,015.5	
24	Detention			
21.	Designed to National Accreditation Standards	CANCE SOME SERVICE		
	to mational motionatation oranged		5 .	
2	Detention Cells	230	360	275
	- Detention Cells: Five (5) required, grouping of two (2) one (1),		- 1	
	and one (1), sight and sound separation between groupings.			
1	- Handicapped accessible detention cell: One (1) required, sight		9	


SPACE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
and sound separation between handicap cell and other cells. - Cell features: a. Secured bunk with closed base b. Security penal fixture with integral sink, remote flush capabilities c. Impact resistant lighting and institutional type fire suppression d. Two way audio communication e. CCTV surveillance f. No floor drains g. 50 SF (min) h. Solid fronts (suicide prevention) i. Sliding doors j. Independent supply and return air, negative pressure within cells		GOMETEL	
3 Detention Area		210	210
- Floor drains - Hose bibb (secured) - Exhaust fan - Impact resistant lighting - Blanket storage cabinet 4 Matron Room - Visual monitoring of cells through CCTV monitor - Dual use as Interview Room		65	65
22. Evidence and Property			
Evidence Receiving Adjacent to Prisoner Processing / Detention / Patrol Areas Temporary evidence lockers (varied sizes), through-wall configuration preferred Refrigerated temporary evidence locker Computer workstation for one (1) Countertop work area Casework storage cabinets for equipment storage		150	130
Evidence Processing / Forensics Lab Secure access to room Fume hood with base cabinet, direct exhaust Epoxy resin countertop with integral sink Storage cabinets Evidence drying cabinet Fuming chamber, countertop model Biohazard disposal containers Adjacent to Evidence Storage / Evidence Receiving		225	200
Secure access to room CCTV monitoring One means of entry only Refrigerated storage High density storage shelving for firearms, evidence containers, valuables Double locking of firearms and ammunition Double locking of valuables No storage of narcotics, off-site location	85	400	350


SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
4	Bulk Evidence Storage	460	400	400
	- Accessibility from exterior	400	400	400
	- Secured access			
	- CCTV monitoring			
	 Double door entry Industrial type adjustable shelving 			
	- Floor drain			
5	Vehicle Processing		See Sally Port	
	- See Sally Port			
23.	Explorers Area			
1	Explorers			565
1	Characa			440
2	Storage			140
24.	Toilets and Custodial Services			
1	Custodial Office		150	150
	- Work area for two (2) custodial staff			
	- Service sink			
	- Workbench - Equipment storage			
	Equipment storage	Chemist 1		
2	Janitor Closets Two (2) @ 50	35	100	80
	- One per floor (minimum)			
	- Floor sink - Custodial supply storage			
	- Custoural supply storage - Cart storage			
	- Equipment storage			
2000				
3	Toilet Facilities Two (2) @75		150	120
	 Civilian Staff / Official visitor's facilities to be provided, one per sex per floor, handicap accessible 			
	- Public facilities within Public Lobby			
	- Patrol staff facilities within Locker Rooms			
	- Administrative staff facilities within Administrative Area			
	- Dispatch staff facilities within Communications Dispatch Center			
	 Detained persons facilities within detention cells and Prisoner Processing 			
	11000001119			
25.	Bulk Storage			
1			250	250
	 Storage of vehicle parts, vehicle equipment, operational equipment, spare parts, child car seats, homeland security 			
	equipment, spare parts, child car seats, nomeland security equipment			
	- Accessible from exterior			
	- Double door access			
	- Access controlled			
26.	Storage Bays		der Garage State Co	
1	Storage Bays		1,000	750
	- Storage of department motorcycles, two (2) minimum		•	
	- Storage of patrol bicycles, two (2) minimum	是自义为为世		
1	- Storage of Mobile Command Van, one (1) minimum			


SPA	CE DESCRIPTION	EXISTING SQUARE FEET	2008 STUDY SQUARE FEET	RECOMMENDED SQUARE FEET
	- Storage of speed trailer, one (1) minimum - Power for recharging of equipment - Overhead door access - Access control at points of entry - Adjacent to staff vehicle parking, staff entry locations			
27.	Circulation			
1	Stairs		e e en encara de la la	
	- Code required minimum, two per floor - 48" clear width (min.)			
2	Elevators		apt with me to his	
	 Access controlled to secure floors Public use, access controlled Sized to accommodate stretcher dimensions Automatic recall Elevator machine room adjacent to shaft 			
28.	Mechanical			
1	Boiler Room	220	500	500
	- Two boilers (min), preferred - Dual-fuel burners if utilities exist - Hot water storage - Floor drains - Chimney breaching		7 m	
2	HVAC Equipment	550	800	800
	Ducted supply and returns High efficiency filters, pumps, and motors VAV boxes with DDC controls Zoned systems throughout facility Host computer for monitoring and diagnosis of systems			
3	Emergency Electrical Room	190	150	150
	Automatic transfer switch Emergency power panels and circuits Diesel fired generator on exterior pad mount (see site needs)			
4	Fire Suppression Fully sprinkled facility according to NFP A 13 standards FM 200 fire suppression within data and communications equip. rooms Institutional type sprinklers in high risk / detention areas Sprinkler control valve assembly and backflow preventor Fire Department siamese connection at designated location		150	150

SPACE NEEDS SUMMARY AND COMPARISON

FUNCTIONAL AREAS	SQUARE FEET	2008	RECOMMENDED
	EXISTING	PROPOSED SQ. FT.	SQ. FT.
1. Public	216	755	660
2. Training Classroom	670	1,685	1,475
3. Main Desk	0	65	65
4. Communications Dispatch Center	665	1,155	0
5. Records Division	430	600	600
6. Administration	1,325	1,655	1,350
7. Administrative Lieutenant	230	225	185
8. Operational Lieutenant	0	225	185
9. Administrative Sergeant	100	175	150
10. Detective Division	710	1,875	1610
11. Traffic Unit	800	325	325
12. Crime Prevention Office	0	200	180
13. Technology Coordinator	0	200	120
14. Computer Equipment Server Room	145	315	145
15. Patrol Functions	1,780	4,405	4,710
16. Union Space	0	65	65
17. Indoor Firearms Training Range	0	1,795	1725
18. Armory / Arsenal	120	150	150
19. Sally Port	300	1,050	950
20. Prisoner Processing	180	705	495
21. Detention	230	635	550
22. Evidence and Property	545	1,175	1080
23. Explorers Area			705
24. Toilets and Custodial Services	35	400	350
25. Bulk Storage	0	250	250
26. Storage Bays	0	1,000	750
27. Circulation	Net to gross	Net to gross	Net to gross
28. Mechanical	910	1,600	1,600
TOTAL NET SQUARE FOOTAGE	9,391	22,685	20,430
Net to Gross Factor (Stairs, Corridors, Ducts, Wall Thickness)	-	X 1.30	X 1.30
TOTAL GROSS SQUARE FOOTAGE REQ'D	2000年1980年	29,500	26,559







D·R·A

Drummey Rosane Anderson 225 Oakland Road Studio 205 South Windsor, CT 06074

. . . .

Planning Architecture Interior Design e-mail: website:

860-644-8300 PHONE 860-644-8301 FAX info@draws.com www.DRAarchitects.com

RE: BUDGET

POLICE DEPARTMENT

(2015 PRICING)

BUDGET

DESCRIPTION		COST
Project Cost Plan (Hard Cost)		\$9,842,000
Soft Cost - A/E Fees (7%) - Clerk of Works (Lump Sum) - Survey - Test Borings - Testing	688,940 120,000 7,000 8,000 20,000	843,940
Computer Systems/Security		175,000
Furnishings @ \$15/SF		375,000
Moving Expense		50,000
Bonding Cost		50,000
Miscellaneous Reimbursables		20,000
	TOTAL	\$11,355,940

COSTPRO INC. TOWN HALL SOUTH CONVERSION & EXPANSION to NEW POLICE DEPARTMENT RENOVATION AND ADDITIONS NEWTOWN, CT



Project:	Project: Firing Range Alternate			Date:	Oct-15		Sheet No: 2 OF 2	2 OF 2	
Uniforma	Jniformat Element (Levels 2&3)	Amount	Total Cost	Rate \$/SF		%	Element Unit	Unit	Element
		\$	S	Floor Area	æ		Quantities		Unit Rate
F SPE	SPECIAL CONSTRUCTION & DEMOLITION		62,500		10.92	3.9%			
F10	F10 Special Construction	0		00.0			0	0 SF	0.00
F20	F20 Selective Demolition	62,500		10.92			2,500 SF	SF	25.00
G BUII	BUILDING SITEWORK		50,000		8.74	3.1%			
G10	G10 Site Preparation	12,500		2.18			2,500 SF	SF	5.00
G20) Site Improvements	37,500		6.55			2,500 SF	SF	15.00
G30	G30 Site Civil/Mechanical Utilities	0		00.00			0	0 SF	00.00
G40	Site Electrical Utilities	0		0.00			0	SF	00.00
065	G90 Other Site Construction	0		0.00			0	SF	0.00
SUE	SUBTOTAL		1,463,750		255.86	90.3%			
Z10 GEN	Z10 GENERAL REQUIREMENTS & BOND	11.47%	167,951		29.36				
Z20 OVE	Z20 OVERHEAD & PROFIT	15.00%	244,755		42.78				
Z30 COL	Z30 CONTINGENCIES & ESCALATION	16.48%	309,240		54.05				
Z40 SOF	Z40 SOFT COSTS	30.00%	655,709		114.61				
Z90 PRC	Z90 PROJECT COST ESTIMATE	\$	2,841,405	<u>~</u>	496.66				

•

Project Cost Plan (Uniformat II Level 3) cosmno, INC.

Project: Firing Range Alternate	GFA(SF):	2,500 Date:		Oct-15		Sheet No: 1 OF 2	OF 2	
Jniformat Element (Levels 2&3)	Amount	Total Cost	Rate \$/SF	8	%	Element Unit	Jnit	Element
	\$	\$	Floor Area			Quantities		Unit Rate
SUBSTRUCTURE		773,925	1	135.28	47.7%			
A10 Foundations	60,950		10.65			2,500 SF	Ľ,	24.38
A20 Basement Construction	712,975		124.62			2,500 SF	ļĻ.	285.19
SHELL		197,650		34.55	12.2%			
B10 Superstructure	60,150		10.51			2,500 SF	ų.	24.06
B20 Exterior Closure	0		0.00			0 SF	Щ.	81.04
B30 Roofing	137,500		24.03			2,500 SF	يا	55.00
INTERIORS		145,725		25.47	9.0%			
C10 Interior Construction	75,050		13.12			2,500 SF	L.	30.02
C20 Stairs	0		00.0			0 FLT	LT	32500.00
C30 Interior Finishes	70,675		12.35			2,500 SF	L.	28.27
SERVICES		172,500		30.15	10.6%			
D10 Conveying Systems	0		0.00			0 8	0 STOP	42750.00
320 Plumbing	0		00:00			0 SF	Щ	22.85
330 HVAC	95,000		16.61			2,500 SF	ΙL	38.00
340 Fire Protection	15,000		2.62			2,500 SF	ш	00.9
D50 Electrical Systems	62,500		10.92			2,500 SF	ш.	25.00
EQUIPMENT & FURNISHINGS		61,450	100	10.74	3.8%			
E10 Equipment	51,500		9.00			2,500 SF	ш	20.60
E20 Furnishings	9,950		1.74			2,500 SF	L	3.98



Project Cost Plan (Uniformat II Level 3) cosmo, INC.

		Date:	Oct-15		Sheet No:	2 OF 2	
Amount	Total Cost	Rate \$/SF		%	Element	Unit	Element
\$	\$	Floor Area			Quantities		Unit Rate
	415,820		20.00	8.0%			
0		00.0			0	SF	0.00
415,820		20.00			20,791	SF	20.00
	392,950		18.90	7.5%			
18,712		06:0			20,791	SF	0.90
311,865		15.00			20,791	SF	15.00
62,373		3.00			20,791	SF	3.00
0		00.0			20,791	SF	0.00
0		0.00			0	SF	0.00
	5,228,589		251.48	100.0%			
11.47%	599,928		28.86				
15.00%	874,278		42.05				
16.48%	1,104,621		53.13				
30.00%	2,342,225		112.66				
8	10,149,641	\$	488.17				
		mount Total Cost \$ 415,820 415,820 392,950 18,712 311,865 62,373 0 0 11.47% 599,928 15.00% 874,278 16.48% 1,104,621 30.00% 2,342,225	mount Total Cost \$ 415,820 415,820 392,950 18,712 311,865 62,373 62,373 11.47% 5,228,589 11.47% 5,228,589 15.00% 874,278 16.48% 110,149,641	Mount Total Cost Rate \$/SF Floor Area 415,820	Date: Oct-15 Amount Total Cost Rate \$/SF % 415,820 0.00 18.90 415,820 0.00 18.90 18,712 0.90 18.90 62,373 300 251.48 11.47% 599,928 251.48 15.00% 874,278 42.05 16.48% 1,104,621 53.13 30.00% 2,342,225 112.66 10,149,641 488.17	Date: Oct-15 Amount Total Cost Rate \$/SF % 415,820 20.00 8.0% 415,820 20.00 8.0% 18,712 20.00 7.5% 62,373 392,950 18.90 7.5% 11.47% 599,928 251.48 100.0% 15.00% 874,278 28.86 11.04,621 30.00% 2,342,225 28.86 112.66 10,149,641 488.17 488.17	Date: Oct-15 Amount Total Cost Rate \$/SF % 415,820 20.00 8.0% 415,820 20.00 8.0% 18,712 20.00 7.5% 62,373 392,950 18.90 7.5% 11.47% 599,928 25.1.48 100.0% 15.00% 874,278 42.05 16.48% 1,104,621 53.13 30.00% 2,342,225 488.17

Project Cost Plan (Uniformat II Level 3) cosmo, INC.

Pr	Project: Renovation Component	GFA(SF):	20,791 Date:	Date:	Oct-15		Sheet No: 1	1 OF 2	
5	Uniformat Element (Levels 2&3)	mount	Total Cost	Rate \$/SF		%	Element	Unit	Element
		↔	es.	Floor Area	a		Quantities		Unit Rate
٧	SUBSTRUCTURE		12,356		0.59	0.5%			
	A10 Foundations	12,356		0.59			11,233 SF	SF	1.10
	A20 Basement Construction	0		0.00			0	0 SF	00.00
Ш	SHELL		809,083		38.92	15.5%			
<u> </u>	B10 Superstructure	0		0.00			0	SF	0.00
	B20 Exterior Closure	809,083		38.95			12,375 SF	SF	65.38
	B30 Roofing	0		00.0			0	SF	12.59
ပ	INTERIORS		1,399,567		67.32	26.8%			
	C10 Interior Construction	680,905		32.75			20,791 SF	SF	32.75
	C20 Stairs	130,900		6.30			2	2 FLT	65450.00
	C30 Interior Finishes	587,762		28.27			20,791 SF	SF	28.27
Ω	SERVICES		1,990,903		92.76	38.1%			
	D10 Conveying Systems	81,250		3.91			0	2 STOP	40625.00
	D20 Plumbing	475,074		22.85			20,791	SF	22.85
	D30 HVAC	790,058		38.00			20,791 SF	SF	38.00
	D40 Fire Protection	124,746		00'9			20,791 SF	SF	6.00
	D50 Electrical Systems	519,775		25.00			20,791 SF	SF	25.00
ш	EQUIPMENT & FURNISHINGS		207,910		10.00	4.0%			
	E10 Equipment	104,995		5.05			20,791 SF	SF	5.05
	E20 Furnishings	102,915		4.95			20,791 SF	SF	4.95

NEWTOWN, CT				Project C	ost Pla	n (Uniform	Project Cost Plan (Uniformat II Level 3)	COSTPRO, INC.
Project: New Addition Component			Date:	Oct-15		Sheet No: 2 OF 2	2 OF 2	
Uniformat Element (Levels 2&3)	Amount	Total Cost	Rate \$/SF		%	Element Unit	Unit	Element
	\$	\$	Floor Area	g		Quantities		Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION	1	0		0.00	0.0%			
F10 Special Construction	0		0.00			0	SF	0.00
F20 Selective Demolition	0		00'0			0	0 SF	2.95
G BUILDING SITEWORK		131,583		23.00	8.1%			
G10 Site Preparation	28,605	100	2.00			5,721 SF	SF	5.00
G20 Site Improvements	85,815		15.00			5,721 SF	SF	15.00
G30 Site Civil/Mechanical Utilities	17,163		3.00			5,721 SF	SF	3.00
G40 Site Electrical Utilities	0		00.0			5,721 SF	SF	0.00
G90 Other Site Construction	0		0.00			5,721 SF	SF	0.00
SUBTOTAL		1,621,817		283.48	100.0%			
Z10 GENERAL REQUIREMENTS & BOND	11.47%	186,087		32.53				
Z20 OVERHEAD & PROFIT	15.00%	271,186		47.40				
Z30 CONTINGENCIES & ESCALATION	16.48%	342,634		59.89				
Z40 SOFT COSTS	30.00%	726,517		126.99				
Z90 PROJECT COST ESTIMATE	€9	3,148,241	↔	550.30				

Project Cost Plan (Uniformat II Level 3) cosmico, INC.



	Element	Unit Rate		24.38	285.19		24.06	81.04	30.00		32.75	32500.00	28.27		42750.00	22,85	38.00	9.00	25.00		5.05	4.95
Sheet No: 1 OF 2	Element Unit	es		2,091 SF	0 SF		5,721 SF	3,789 SF	2,091 SF		5,721 SF	0 FLT	5,721 SF		0 STOP	5,721 SF	5,721 SF	5,721 SF	21 SF		5,721 SF	5,721 SF
Sheet N	Elemer	Quantities	3.1%	2,0		3%	5,7	3,7	2,0		5,7		5,7			5,7	5,7	5,7	5,721	3.5%	5,7,	5,7
Oct-15	%		8.91 3.			88.70 31.3%				61.02 21.5%				91.85 32.4%						10.00		
	Rate \$/SF	Floor Area		8.91	00.0	Ø	24.06	53.68	10.96	9	32.75	0.00	28.27	6	0.00	22.85	38.00	6.00	25.00	1(5.05	4.95
5,721 Date:	otal Cost	⊕	50,979			507,475				349,096				525,474						57,210		
GFA(SF):	mount	↔		50,979	0		137,647	307,098	62,730		187,363	0	161,733		0	130,725	217,398	34,326	143,025		28,891	28,319
Project: New Addition Component	Uniformat Element (Levels 2&3)		SUBSTRUCTURE	A10 Foundations	A20 Basement Construction	SHELL	B10 Superstructure	B20 Exterior Closure	B30 Roofing	INTERIORS	C10 Interior Construction	C20 Stairs	C30 Interior Finishes	SERVICES	D10 Conveying Systems	D20 Plumbing	D30 HVAC	D40 Fire Protection	D50 Electrical Systems	EQUIPMENT & FURNISHINGS	E10 Equipment	E20 Furnishings



Project Cost Plan (Uniformat II Level 3) costreso, INC.

Project: Renovation And Addition			Date:	Oct-15		Sheet No: 2 OF 2		
Uniformat Element (Levels 2&3)	Amount	Total Cost	Rate \$/SF		%	Element Unit	Ш	Element
	↔	↔	Floor Area	æ		Quantities	<u> </u>	Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		415,820		15.68	6.1%			
F10 Special Construction	0		0.00			0 SF		0.00
F20 Selective Demolition	415,820		15.68			20,791 SF		20.00
G BUILDING SITEWORK		524,533		19.78	7.7%			
G10 Site Preparation	47,317		1.78			26,512 SF		1.78
G20 Site Improvements	397,680		15.00			26,512 SF		15.00
G30 Site Civil/Mechanical Utilities	79,536		3.00			26,512 SF	••	3.00
G40 Site Electrical Utilities	0		0.00			26,512 SF		0.00
G90 Other Site Construction	0		0.00			5,721 SF		0.00
SUBTOTAL		6,850,406		258.39	100.0%			
Z10 GENERAL REQUIREMENTS & BOND	11.5%	786,015		29.65				
Z20 OVERHEAD & PROFIT	15.0%	1,145,464		43.21				
Z30 CONTINGENCIES & ESCALATION	16.5%	1,447,255		54.59				
Z40 SOFT COSTS	30.0%	3,068,742		115.75				
Z90 PROJECT COST ESTIMATE	\$	13,297,882	↔	501.58				



Project Cost Plan (Uniformat II Level 3) costreo, INC.

P	Project: Renovation And Addition	GFA(SF):	26,512 Date:	Date:	Oct-15		Sheet No: 1 OF 2	1 OF 2	
5	Uniformat Element (Levels 2&3)	Amount	Total Cost	Rate \$/SF		%	Element	Unit	Element
		()	s	Floor Area	a		Quantities		Unit Rate
⋖	SUBSTRUCTURE		63,335		.2.39	%6.0			
	A10 Foundations	63,335		2.39		•	13,324 SF	SF	4.75
	A20 Basement Construction	0		00.0			0	0 SF	0.00
В	SHELL		1,316,558		49.66	19.2%			
	B10 Superstructure	137,647		5.19			5,721 SF	SF	24.06
	B20 Exterior Closure	1,116,181		42.10			16,164 SF	SF	69.05
	B30 Roofing	62,730		2.37			2,091 SF	SF	30.00
ပ	INTERIORS		1,748,663		65.96	25.5%			
	C10 Interior Construction	868,268		32.75			26,512 SF	SF	32.75
	C20 Stairs	130,900		4.94		•	CI	2 FLT	65450.00
	C30 Interior Finishes	749,495		28.27			26,512 SF	SF	28.27
Ω	SERVICES		2,516,377		94.91	36.7%			
	D10 Conveying Systems	81,250		3.06			2	2 STOP	40625.00
	D20 Plumbing	605,799		22.85			26,512 SF	SF	22.85
	D30 HVAC	1,007,456		38.00			26,512 SF	SF	38.00
	D40 Fire Protection	159,072		00.9			26,512 SF	SF	6.00
	D50 Electrical Systems	662,800		25.00			26,512 SF	SF	25,00
ш	EQUIPMENT & FURNISHINGS		265,120		10.00	3.9%			
	E10 Equipment	133,886		20.3			26,512 SF	SF	5.05
	E20 Furnishings	131,234		4.95			26,512 SF	SF	4.95

Town of Newtown, Connecticut

TOWN HALL SOUTH

3 Main Street

Year Constructed: 1950

Year of Renovation/Addition: 1990 Building Type: B/S-2/R-2

Construction Type:

IIIB

Fire sprinklers:

No

Total Floor Area:

18,528 SF

Floors:

Basement and First Floors

Parking:

53



GENERAL: Originally constructed as a tractor sales building the building was repurposed to serve Town functions including the Police Department. The exterior of the building is suffering from many years of being clad with "Texture 1-11" siding, a product that is basically scored plywood intended to provide an appearance of vertical wood siding. Windows have needed to be replaced due to air and water leakage. In contrast the interiors are in much better condition.

It is very difficult to find parking spaces on the site which we consider to be undersized for its current uses.

LIFE SAFETY:



Stair between Lower and Upper Levels has projecting nosings and only one handrail. There is also insufficient landing space at the bottom and top of the stair. This stair appears to be a service stair that is not used by other than the custodial staff but it does



serve as an egress from what would otherwise be a dead end corridor. As such the stair needs to be upgraded to remove the projecting nosings by using beveled siding to create a gradual slope

from the treads to the nosings. ADA compliant handrails need to be added on both sides. The bottom landing will need to be increased in size to allow for clearance space at the door. Similarly, the door at the top of the stair needs to be removed



Add a new fire rated partition and ceiling in the Janitor's Closet to separate it from the Storage Area.


HEALTH: N/A


Town of Newtown, Connecticut

HAZARDOUS MATERIALS: N/A

ADA COMPLIANCE:

- Shower room at cell area is not accessible for disabled persons. Redesign space to provide full accessibility to shower and fixtures.
- There is no accessible cell for disabled persons. An adjacent area to the detention space will need to be modified to create a cell for disabled persons.
- Shower/Restrooms for men and women are not fully accessible.
 Showers are non-compliant. Restrooms do not meet the Building Code requirements. Redesign Shower/restrooms to fully meet the State Building Code.





The lavatories in the Lower Level Restrooms need to have all piping insulated under the counter.


The Upper Level Restroom for the disabled is not accessible.


Door lever is broken, and sign should have raised letters, symbol, and braille and be mounted on adjacent wall.

The interior of the room is too small to meet ADA and CT Building.

The interior of the room is too small to meet ADA and CT Building Code. Construct new Women's and Men's accessible toilet rooms.










Town of Newtown, Connecticut





Sink in Staff Kitchenette/Workroom is not accessible. Change cabinets to provide knee space and replace sink


SITE:

Parking lot is badly cracked. Loose areas should be removed and cracks cleaned and sealed. Replace base material under loose areas. A new top coat should be applied over entire paved areas.



EXTERIORS:

Exterior siding is deteriorating and is in need of replacement. The north and east sides of Texture 1-11 siding has been redone but the remaining two sides need to be replaced and painted.



Replace damaged exhaust vents




Parging is delaminating from concrete foundation wall.
Remove loose material, apply bonding agent and re-parge exposed concrete areas.





Foundation wall and concrete masonry wall are cracking. Cut a control joint in concrete masonry and apply sealant and backer rod.



Town of Newtown, Connecticut









- Two exterior hollow metal doors and frames need to be re-painted.
- EIFS system needs to be repaired on the exterior wall adjacent to the public restrooms.




INTERIORS:

- Painted concrete floors in cell block area, booking and in hallway behind the cells, are worn and need to be re-painted with epoxy. This also applies to the floor in the Lower Level Custodial Storage room.
- Gypsum wallboard at floor in sally port has deteriorated from moisture. Replace bottom 24 inches with moisture resistant/abuse resistant wallboard with sealant at the floor line. Paint first four feet of wall with epoxy paint.












Town of Newtown, Connecticut





Exterior door lintel in Hallway adjacent to the Fan Room needs 3 to be pointed and re-painted.





Floor tile in Traffic Division's Office and the Pantry needs to be 3 replaced.



Toilet partitions in Lower Level Restrooms are rusted, worn and need to be replaced.

There is evidence of an old water leak in the Lower Level Storage and the walls need to be





There are two areas where the baseboard radiation covers are damaged and need to be 3 replaced. These occur on the east and west side of the building at the exit doors.

ENERGY & WATER CONSERVATION: N/A

MECHANICAL, ELECTRICAL, PLUMBING AND FIRE PROTECTION: (see individual reports for detailed description).


painted.

Town of Newtown, Connecticut

MECHANICAL:




Boiler Plant: The building is heated by one Eighty Eight Series hot water boiler. The boiler is gas fired and reaching the end of its useful life. There are two pumps which provide redundancy in case one pump fails. The hot water system serves fin tube radiation and duct mound hot water coils. The hot water pumps are controlled by six temperature zones via electric relays. Recommend replacing the boiler with two high efficiency condensing boilers to provide redundancy and



higher levels of energy efficiency (up to 95% versus current boilers with nominal efficiently of probably 75% to 80%). Replace hot water distribution and controls to provide more zones for energy efficiency and update controls to DDC type system.



Most of the building is served by indoor mounted air handling units with remote compressor / condensers and duct mounted hot water coils. Most of the units are old are in fair to poor condition. Ductwork distribution to spaces below includes single zone hot water coils. "Local" air conditioning is also provided at specific areas with ductless split units. Temperature control system is via electric relays with electric actuated valves and dampers. Computer Operations Room needs improved air conditioning and ventilation. Recommend replacing air handling systems and replace and upgrade controls to web based DDC type system.



ELECTRICAL:



The building is served by a Square D distribution panel, rated at 400 amperes, 208Y/120 volts, 3-phase. The service equipment and main distribution panels are in good condition.



Town of Newtown, Connecticut

Emergency Generator: The generator is a 80 KW Kohler; gas fired generator and automatic transfer switch located inside; both are in good condition. Recommend upgrading electrical power distribution throughout the building with new local panels, new receptacles and wiring.



Lighting, in general, consists primarily of fixtures with acrylic lenses and T8 fluorescent lamps. Most of the fixtures are in fair to poor condition. Emergency lighting is handled by an emergency generator and local battery pack type fixtures. The fire alarm system is a Honeywell zoned system. There are manual fire alarm pull stations throughout the building. Replace lighting with new energy efficient fixtures and controls such as occupancy sensors and daylight harvesting. Where feasible, replace battery pack type emergency lights and re-circuit fixtures to be fed from the generator.



Replace and upgrade fire alarm system to an addressable system.

PLUMBING:



Existing plumbing fixtures are as follows:


- a. In general, there are a variety of fixtures of different age and condition. Many of the fixtures are in need of replacement due to age and also to benefit from sensor mounted controls and water conserving features.
- b. Water closets are floor mounted; tank type, vitreous china
- c. Lavatories are wall hung and counter mounted vitreous china. Faucets are installed with single lever handle faucets.
- d. Urinals are wall mounted with manual flush valves.

Recommend replacing all plumbing fixtures and water piping.

Town of Newtown, Connecticut



Existing Domestic Hot Water System: The domestic hot water is generated by a Bradford White gas fired water heater with 50 gallon storage. The water heater is in good condition, but does not incorporate a mixing valve at the hot water supply. Recommend adding mixing valve to water heater.





FIRE PROTECTION:




There is no central fire protection system (sprinklers) currently at the facility. We recommend a new wet type fire protection system be installed with sprinklers throughout the entire building.

*

*

*



Order of					
Importance	Description	Value	Fiscal Year	Sequence	
1	Add Mixing Valve to Water Heater	\$ 5,190.00	2016	Sequence	
					\$ 5,
6	Upgrade Stairs to meet ADA Codes	\$ 20,116,00			Control of the Contro
2	Replace Siding and Paint	\$ 157,032.00	2016		
3	New Fire Alarn System	\$ 31,140.00	2016		
4	Install New Fire Rated Partition and Ceiling	\$ 5,198.00			
5	New Sprinkler System	\$ 103,800.00	2017		i
7	Replace Hot Water, Boiler, Dist. and Controls	\$ 155,700.00	2017		
					\$ 472,
8	Upgrade Electrical Power Distribution	\$ 83,040.00			
9	Replace Air Handling System and Controls	\$ 363,300.00	2019		
10	Replace Baseboard Radiation Covers	\$ 2,397.00			
11	Replace Windows	\$ 495,146.00			
12	Replace Toilet Partition	\$ 8,447,00			
13	Replace Lighting with Efficient Fixtures	\$ 62,280.00			
14	Replace Plumbing Fixtures and Water Piping	\$ 155,700.00	2018		
15	Repair Parking Lot Surface	\$ 93,042.00			
16	Redesign Shower room	\$ 30,924.00			
17	Create Cell for Disabled Person	\$ 98,351.00			
18	Residesign Restroom/ Shower Area	\$ 60,081.00			
19	Replace Knobset with Lever sets	\$ 60,974.00			
20	Modify Counter to allow Knee Space	\$ 5,990.00			
21	Install Insulation on Piping under Sinks	\$ 631.00			
22	Construct New ADA Accessible Restrooms	\$ 46,567.00			
23	Install second Handrail on Ramp	\$ 3,662.00			
24	Modify Cabinets and Sink	\$ 4,715.00			
25	Replace Damaged Exhaust Vents	\$ 2,350,00			
26	Re-parge Exposed Concrete	\$ 7,346.00			
27	Cut Control Joint	\$ 4,963.00			
28	Scrape, Prime and Paint	\$ 4,097.00			
29	Repaint Doors	\$ 1,024.00			
30	Repair EIFS System	\$ 3,525.00			
31	Repaint Concrete Floors	\$ 8,753.00			
32	Replace Gypsum Wall Board and Paint	\$ 4,136.00			
33	Replace Louvers	\$ 2,933.00			
34	Replace Ceiling Panels	\$ 3,723.00			
35	Paint Walls	\$ 9,161.00			
36	Investigate Wall Where Efforescence is Present	\$ 9,314.00			
37	Re-point and Paint Lintel	\$ 514,00			
38	Replace VCT or Vinyl Flooring	\$ 14,505.00			

Total \$ 2,129,767.00

Town of Newtown								
Capital Needs Survey Fo	rm							Total Floor Area (sf):
Town Hall South								10,380
Note: The "System Priority Rating" (1 to	o 4 ratin	g) and '	'Conditi	on of th	e Existi	na System	Rating" (1	to 5 rating) are to be reviewed
together to assist in prioritizing replacer	nent and	d/or upo	rades.	As an e	example	we recor	nmend line	items with a System Priority rating of
1 and Existing Conditions rating of 1 be	prioritiz	ed for r	enlacen	nent an	d/or upo	rades		none was a cyclost t tionly rating of
Tana Existing Conditions rating of 1 be	T		Chiaccii	TOTIC OFF	u/or upg	jiaucs.		
	4	to 5	-	Ħ	ŀ		+=	
	2 -		ea	Ĕ	ŀ		Ē	
		e = 5	ے	ğ			i i	
	System Priority (1-Highest Priority 4-Lowest Priority)	Condition of the Existing System 1 (1 Poor, 5 Excellent)	Last Major Reconstruction (Year)	Projected Replacement (Year)			Current Replacement Cost	
	16 2 2	D S A	7 2	<u>~</u>		6	Şe Ş	
	n P P	0.00	str	<u> </u>	- ≥	윤	뒽	
	in the second	黄 崇 喜	25 6	§ €		₽.	<u> </u>	
SYSTEM	IX = 글	[호품문	Last Major Reconstruc	Project (Year)	Quantity	Unit Price	2 2	REMARKS
Division 2 - Site Construction	107 ~ 4	 						NEWAGO
Site - General			22					N/A
			(circa)					
Division 15 -Fire Protection		architecture and other	ar sanstrakturanna zazar	Color de la companio				
Add new FP service and sprinklers throughout	2	2		2017	10,380	\$10	\$103,800	
						ĺ		
Division 15 -Plumbing	 				ļ	<u> </u>		
Replace Plumbing Systems Including:	3	3		2018	10,380	\$15	\$155,700	
Water Distribution System								
Plumbing Fixtures	10000000							li e
Water Heater Mixing Valve	1			2016	10,380	\$0.5	\$5,190	
D	<u> </u>	ļ		<u> </u>	<u> </u>			
Division 15 - HVAC	commonteness.		enematiciones.	and the contact of the	98090000000000000			
Hot Water Boilers, Pumps & Controls	2	2	1978	2017	10,380	\$15	\$155,700	Upgrade / replace boiler plant
General HVAC includes:	3	3	1994	2019	10,380	\$15	\$363,300	Upgrade / replace equipment
Hot Water Heating Elements & Piping		School Charles	1997	2013	Odejei	V00	ψ000,000	Opgrade / replace equipment
Ductwork / VAV Boxes								
Exhaust Systems		12504 (951)						Management of the second secon
Temperature Control Systems								
	<u> </u>	<u> </u>				ļ		
Division 16 - Electrical	0.0000.0000.000	5365363637565756		CASCOS CONTRACTOR		ales dallo ingrise species contra		
General Electrical Distribution	3	3		2020	10,380	\$8	#02.040	
Fire Alarm System	2	2	0.0000000000000000000000000000000000000	2020	10,380	\$8	\$83,040 \$31,140	
Lighting - Replace Fixtures and Control	3	3	COMPANIES OF	2017	10,380	56	\$62,280	
Eigning Tropiace Fixtures and Control	anson O postale	10 (PAI) 4 225166	N/HARRON STREET	LUCU	10,000	ΨU	Ψ02,200	40.00 - 1/20 - 1
	(VACARY 1990/1998)	10/40/00/00/00/00/00/00/00/00/00/00/00/00		nickymen ett fillialist 1990	est sage wert filled in the	HARMINAMERIA DI SIRIFICISI		MANAGER ST. STORY OF STATE STA
	 						\$ 960,150	
								per sf
	!							